## **JOHNSON/EVINRUDE (OMC)**





## Comes complete with two hose clamps

## Features...

- \* Premium all-rubber construction.
- ★ Superior UV resistance.
- Excellent cold-weather flexibility.
- ★ Double check valves. Utilizing a stainless steel spring and viton check balls - resists both corrosion and sticking.
- ★ Superior fuel flow.
- $\star$  Available for 1/4", 5/16" and 3/8" fuel lines.
- Suitable for all makes of outboards.
- All Sierra primer bulbs are engineered and manufactured in our Litchfield facility.
- Alcohol resistant large capacity.
- 🖈 Display packaged



Sierra #	AP#	I.D. Hose	Replaces	Description
18-8002	_	1/4"	_	_
18-8004	_	<sup>5</sup> / <sub>16</sub> "	174511	Large capacity bulb
18-8005	3881	3/8"	174512	Large capacity bulb

AP#	Clamp O.E.#	Clamp Range	Size	Γ
1371	322652	.538608	8	1
1372	911616	.597665	10	
1373	329654	.670780	12	1
1368	322653	.360406	2	1
1369	124249	.410468	4	]
1370	322654	.475536	6	1
_	329653	.750875	14	1
_	324825	.875975	19	
	1371 1372 1373 1368 1369	AP# O.E.# 1371 322652 1372 911616 1373 329654 1368 322653 1369 124249 1370 322654 — 329653	AP# O.E.# Range 1371 322652 .538608 1372 911616 .597665 1373 329654 .670780 1368 322653 .360406 1369 124249 .410468 1370 322654 .475536 — 329653 .750875	AP# O.E.# Range Size   1371 322652 .538608 8   1372 911616 .597665 10   1373 329654 .670780 12   1368 322653 .360406 2   1369 124249 .410468 4   1370 322654 .475536 6   — 329653 .750875 14

PKG. OF 10



**SNAPPER CLAMPS** 

18-8056 AP# 819 FUEL CONNECTOR Replaces: 174508

Fits 5/16" Hose

18-8063 AP# 820 FUEL LINE

FUEL LINE CONNECTOR Replaces: 502867

Display Packaged



18-8055 AP# 844 BRASS HOSE BARB

1/4" NPT Thread for connection of 5/16" Hose Replaces: 173311



AP# 874 90° FUEL ELBOW 3/6" Barb with 3/6" NPT Thread Replaces: 174177



3/8" HOSE BARB with 1/4" NPT Thread Replaces: 173312



³/<sub>8</sub>" Replaces: 176445




Replaces: 910048



18-6525 THROTTLE CABLE Replaces: 397003

For: 4, 85, 115 HP models from 1968 & up



18-6526 THROTTLE CABLE Replaces: 397004

For: 6 & 8 HP models from 1968 - 1990



18-6528 THROTTLE CABLE Replaces: 500081, 396161 For: 20, 25 & 30 HP models from 1986 & up