

VOLVO PENTA Ignition System



 <p>18-5354 AP# 3062 DISTRIBUTOR CAP Replaces: 3854548-9 V-8 Fits new GM style "Module in Cap"</p>	 <p>18-5356 AP# 887 DISTRIBUTOR CAP Replaces: 243797-8</p>	 <p>18-5357 AP# 1096 DISTRIBUTOR CAP Replaces: 870690-5</p>	 <p>18-5358 DISTRIBUTOR CAP Replaces: 841263-7</p>
 <p>18-5361 AP# 3060 DISTRIBUTOR CAP Replaces: 3854260-1 For: 3.0L</p>	 <p>18-5362 AP# 3061 DISTRIBUTOR CAP Replaces: 3854331-0 V-6 Fits new GM style "Module in Cap"</p>	 <p>18-5369 AP# 893 DISTRIBUTOR CAP Replaces: 835702-2 with 18-5399 Gasket</p>	 <p>18-5375 AP# 868 DISTRIBUTOR CAP Replaces: 841244-7</p>
 <p>18-5393 DISTRIBUTOR CAP Replaces: 241669-1</p>	 <p>18-5394 DISTRIBUTOR CAP Replaces: 243658-2</p>	 <p>18-5434 IGNITION COIL Replaces: 835998-6 Uses External Resistor</p>	 <p>18-5436 IGNITION COIL Replaces: 35254-2 Has Internal Resistor</p>
 <p>18-5443 AP# 3756 IGNITION COIL Replaces: 3854002-7 3.0L/4.3L/5.7L/7.4L</p>	 <p>18-5107-1 AP# 13348 IGNITION MODULE</p>	 <p>18-5108 AP# 13350 SENSOR (Pick-Up Coil)</p>	

SEE PAGE 686 FOR APPLICATION